863 Valley View Rd, Eighty Four, PA 15330
724-941-9701
www.skcinc.com

PERMEA-TEC Sensor for o-Phthalaldehyde
Cat. No. 769-3009
Operating Instructions

Performance Profile

Expiration	Limited shelf-life; check expiration date on packaging
Storage	Ambient temperature **Caution:** Do not store with food.
Stability	Stable at ambient conditions
Known Interferents	None

How To Use Sensors

To determine a user-safe time period for the particular glove, ***double gloving is recommended.***

1. Affix PERMEA-TEC sensors to the thumb, middle finger, and palm on the outside of the glove currently being worn. Place the glove to be evaluated over the first glove.
2. After one hour, remove the outside glove and the underlying PERMEA-TEC sensors.
3. Lightly spray PERMEA-TEC sensors with Cleaning/Developing Solution for o-Phthalaldehyde 769-1069 or 769-1055.
4. Allow 10 to 15 minutes for color development. ***Note:*** *Read results only within the test window of 15 minutes.*

5. Evaluate the sensors for breakthrough. A positive indication of breakthrough results in a color change to **red**.
6. If no breakthrough is indicated, apply fresh PERMEA-TEC sensors and continue to wear the outside glove for another hour. Follow Steps 2 through 5 to determine if breakthrough has occurred.
7. Repeat Steps 5 and 6 to determine a user-safe time period for gloves.

To see the SWYPE Semi-Quantitative Color Reactions chart, click here or go to www.skcinc.com/surface-dermal.

Lowest Detection Limit (LDL)

Chemical Hazard	LDL (µg)
o-Phthalaldehyde	100

Ordering Information

Description	Cat. No.
Cleaning/Developing Solution, o-Phthalaldehyde, 22 oz	769-1069
Cleaning/Developing Solution, o-Phthalaldehyde, 1 gal	769-1055

SKC Limited Warranty and Return Policy
SKC products are subject to the SKC Limited Warranty and Return Policy, which provides SKC's sole liability and the buyer's exclusive remedy. To view the complete SKC Limited Warranty and Return Policy, go to www.skcinc.com/warranty-information.