



863 Valley View Rd, Eighty Four, PA 15330
724-941-9701
skcinc.com

Surface SWYPE for Acid/Base Cat. No. 769-1026 Operating Instructions

Limited shelf-life: Check expiration date on packaging.

1. Lightly spray the area or item (e.g., workbench, tool, control knob) with Developing Solution for Acid/Base Cat. No. 769-1066.
2. Wait at least 30 seconds and then wipe with a Surface SWYPE pad.
3. The acid detector will change from neutral (orange) color to fuchsia/magenta at pH 3. For caustic exposures, the indicator will change to blue at pH 9.5.

SKC Limited Warranty and Return Policy

SKC products are subject to the SKC Limited Warranty and Return Policy, which provides SKC's sole liability and the buyer's exclusive remedy. To view the complete SKC Limited Warranty and Return Policy, go to skcinc.com/warranty.