



Surface SWYPE for Nickel Cat. No. 769-1028

1. Lightly spray the area or item (e.g., workbench, tool, control knob) with Cleaning/Developing Solution for Nickel Cat. No. 769-1068 or 769-1054.
2. Wait at least 30 seconds and then wipe with a Surface SWYPE pad.
3. Allow 3 minutes for the color to develop on the pad. Nickel will produce the following color:
 - Pink

Note: Although the color is stable, it is recommended that you read the color after 3 minutes.

SKC Limited Warranty and Return Policy

SKC products are subject to the SKC Limited Warranty and Return Policy, which provides SKC's sole liability and the buyer's exclusive remedy. To view the complete SKC Limited Warranty and Return Policy, go to skcinc.com/warranty.