



863 Valley View Rd, Eighty Four, PA 15330
724-941-9701
skcinc.com

DECONTamination Solution for Aromatic Amines Cat. Nos. 769-1051, 769-1051D, and 769-1071 Operating Instructions

Limited shelf-life: Check expiration date on packaging.

Cleaning/Decontamination

1. Wet area thoroughly with Cleaning/Developing Solution for Aromatic Amines Cat. No. 769-1041 or 769-1061. Use an abrasive pad if necessary to enhance penetration. Do not rinse before applying DECONTamination solution.
2. Spray the area with DECONTamination solution and allow it to react for at least 5 minutes. Rinse with water.
3. Recheck the area with Surface SWYPE Cat. No. 769-1021 to verify decontamination is complete. If contamination is still present, repeat Steps 1 and 2.
4. To decontaminate tools, mix 1 part DECONTamination solution with 3 parts cleaning/developing solution in a closed container. Let tools soak for approximately 5 minutes and rinse with water. Recheck with Surface SWYPE to verify decontamination is complete.

SKC Limited Warranty and Return Policy

SKC products are subject to the SKC Limited Warranty and Return Policy, which provides SKC's sole liability and the buyer's exclusive remedy. To view the complete SKC Limited Warranty and Return Policy, go to skcinc.com/warranty.

Form 37562 Rev 241112